

DSM ENVIRONMENTAL SERVICES, LLC
2003 HIGHLAND PLACE
VICKSBURG, MS 39180

INVOICE

REQUISITION #
General (BY)
4/25/25
2505212

Bill To: City of Vicksburg
P.O. Box 150
Vicksburg, MS 39180

Date: April 25, 2025

Invoice Number: 25-338

Purchase order # (N/A)

SERVICES RENDERED:

Inspect Residential Structure located at 2057 Sky Farm Avenue for the presence of Suspected Asbestos Containing Material. Obtain and submit representative samples to a Certified Lab for analysis; Prepare Asbestos Inspection Report.

*Inspect Structure	\$850.00
*Submit Samples for Analysis- 6 samples @ \$50.00/ sample	<u>\$300.00</u>

TOTAL THIS INVOICE: **\$1,150.00**

Due Upon Receipt

Thanks,
DSM Environmental Services, LLC

APPROVED AND ACCEPTED IN
COMMUNITY DEVELOPMENT

APR 28 2025


RECEIVED AND ACCEPTED IN
COV HOUSING DEPARTMENT

APR 25 2025
BY: *Carol W. Harris*

DSM ENVIRONMENTAL SERVICES, LLC
2003 Highland Place
VICKSBURG, MS 39180
VETERAN OWNED BUSINESS

Phone: 601-529-2278

Email: ddmiller@cablelynx.com Mobile: 601-529-2279

April 25, 2025

Carolyn
Ms. ~~Caroline~~ Harrison *and*
City of Vicksburg
Housing Department
Vicksburg, MS 39180

Asbestos Inspection of Kathleen Goodwin Residence 2057 Sky Farm Ave.

DSM Environmental Services, LLC submits this Asbestos Inspection Report for the residential structure located at 2057 Sky Farm Avenue, Vicksburg, MS.

The inspection included obtaining representative sample of Suspected Asbestos Containing Material (SACM) and sending them to a Certified Laboratory for analysis for the presence of asbestos. The analysis was performed using the Polarized Light Method (PLM) to determine whether or not material deemed to be Asbestos Containing Material (ACM) under current EPA, MDEQ and OSHA regulations is present. Under current regulations, before a building can be renovated or demolished it must be inspected for ACM.

Areas inspected included bath room floor, living room floor, living room ceiling, interior room ceiling and roofing. Representative samples of listed areas were obtained and submitted for analysis.

Analysis of the representative samples revealed **No Evidence of Asbestos Containing Material**.

Upon submission of Mississippi Asbestos Demolition/Renovation Notification Form and MDEQ acknowledgement, renovation may proceed as planned.

DSM Environmental Services, LLC will submit notification form to MDEQ.

DSM ENVIRONMENTAL SERVICES, LLC

Don S. Miller Jr.
Don S. Miller, Jr.
Certified Asbestos Inspector

RECEIVED AND ACCEPTED IN
COV HOUSING DEPARTMENT

APR 25 2025

BY: *Carolyn W. Harrison*



7469 Whitepine Rd
North Chesterfield, VA 23237
Telephone: 800.347.4010

Asbestos Bulk Analysis Report

Report Number: 25-04-03564

Client: DSM Environmental Services LLC
2003 Highland Place
Vicksburg, MS 39180

Received Date: 04/18/2025
Analyzed Date: 04/23/2025
Reported Date: 04/23/2025

Project/Test Address: **Kathleen Goodwin** Residence; 2057 Sky Farm Ave; Vicksburg, MS

Client Number:
25-6759

Fax Number:
601-636-6211

Laboratory Results

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
25-04-03564-001	25-338-1		Beige Vinyl; White Foam; Inhomogeneous	NAD	5% Fibrous Glass 95% Non-Fibrous
25-04-03564-002A	25-338-2	Tile	Beige/Green Vinyl; Homogeneous	NAD	1% Synthetic 99% Non-Fibrous
25-04-03564-002B	25-338-2	Mastic	Brown Adhesive; Homogeneous	NAD	3% Cellulose 2% Hair 95% Non-Fibrous
25-04-03564-003	25-338-3		Beige/White Chalky; Inhomogeneous	NAD	100% Non-Fibrous
25-04-03564-004	25-338-4		Brown Fibrous; Homogeneous	NAD	99% Cellulose 1% Non-Fibrous

RECEIVED

APR 28 2025

Chenille BY

Environmental Hazards Services, L.L.C

Client Number: 25-6759
Project/Test Address: Kathleen Goodwin Residence; 2057 Sky
Farm Ave; Vicksburg, MS

Report Number: 25-04-03564

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
25-04-03564-005	25-338-5		Black Tar-Like; Tan/Gray Aggregate; Inhomogeneous	NAD	15% Fibrous Glass 85% Non-Fibrous

QC Sample: 98-M22012-1

QC Blank: SRM 1866 Fiberglass

Reporting Limit: 1% Asbestos

Method: EPA Method 600/R-93/116, EPA Method 600/M4-82-020

Analyst: Kathy Fletcher

Reviewed By Authorized Signatory:



Tasha Eaddy
QA/QC Clerk

These results are based on a comparative visual estimate. The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Each distinct component in an inhomogeneous sample was analyzed separately and reported as a composite. Results represent the analysis of samples submitted by the client. Sample location, description, area, volume, etc., was provided by the client. This report cannot be used by the client to claim product endorsement by NVLAP or any agency of the U.S. Government. This report shall not be reproduced except in full, without the written consent of the Environmental Hazards Service, L.L.C. All information concerning sampling location, date, and time can be found on Chain-of-Custody. Environmental Hazards Services, L.L.C. does not perform any sample collection. . NVLAP #101882-0 VELAP 460172


Environmental Hazards Services, L.L.C. recommends reanalysis by point count (for more accurate quantification) or Transmission Electron Microscopy (TEM), (for enhanced detection capabilities) for materials regulated by EPA NESHAP (National Emission Standards for Hazardous Air Pollutants) and found to contain less than ten percent (<10%) asbestos by polarized light microscopy (PLM). Both services are available for an additional fee.

400 Point Count Analysis, where noted, performed per EPA Method 600/R-93/116 with a Reporting Limit of 0.25%.

LEGEND: NAD = no asbestos detected

RECEIVED

APR 28 2025

 BY